

Final 1998 Section 303(d) List - WRIA 44

Water Name	COLUMBIA RIVER		
Parameter	Temperature	Mediu	Water
Place on 1998 List?	<input type="checkbox"/> Yes	Listed in 1996	<input type="checkbox"/> Yes Action Needed TMDL
New Segment ID #	NN57SG	Old Segment ID #	WA-CR-1050
Stream Route #	715.075	Water Resource Inventory Area	44
Township	21N	Waterbody Grid #	
Range	22E	Grid Latitude	
Section	16	Grid Longitude	
Basis for Consideration of Listing	2 excursions beyond the criterion at Ecology ambient monitoring station 44A070 (RM 450.9) on 7/16/90 and 8/13/90;		
Remarks	The likely cause of these excursions beyond the criterion are due to stratification behind impoundments. Remedies to the problem may not be available.		